ABSTRACT OF THE DISCLOSURE

A method for making a composite tool includes the steps of forming a recess in one of a steel shank and a working body, forming a protrusion on the other of the steel shank and the working body, pressing the protrusion into the recess in such a manner that the protrusion completely fills the recess, and forming a solder joint on a shoulder defined by the steel shank and the working body.